

2009 Nissan Maxima Service Engine Soon Light

2009 Nissan Maxima Service Engine Soon Light - The widest range of products, outstanding quality, and affordable prices are the three pillars on which CARiD bases its work. As a result, we provide an extensive selection of high quality Nissan Maxima repair parts manufactured to restore your vehicle to like new condition at the most attractive prices. Possible Causes and Repair Information for P0300 Nissan code. Learn what does P0300 Nissan means? P0300 Nissan Cylinder Misfire Detected Random Cylinders While early models of the Nissan Maxima were small sedans, newer models are considered luxury sedans. Read more Nissan reviews to learn about other models. This company is not yet accredited. To ... P1143 Nissan Description The Heated Oxygen Sensor 1 is placed into the front tube. It detects the amount of oxygen in the exhaust gas compared to the outside air. The heated oxygen sensor 1 has a closed-end tube made of ceramic zirconia.